

FIG.1


FLAT FOR LOCATING
LOCKING GRUB SCREWS

FIG.2


FLAT FOR LOCATING
LOCKING GRUB SCREWS

FIG.3

Model No.	Morse Taper No.	\varnothing Dmm	\varnothing dmm	Lmm	Fig.
TSOC-C 25 x MT-1	MT-1	32	25	80	1
TSOC-C 25 x MT-2	MT-2	32	25	92	1
TSOC-C 32 x MT-1	MT-1	38	32	76	1
TSOC-C 32 x MT-2	MT-2	38	32	75	2
TSOC-C 32 x MT-3	MT-3	38	32	95	2
TSOC-C 40 x MT-1	MT-1	48	40	90	1
TSOC-C 40 x MT-2	MT-2	48	40	90	1
TSOC-C 40 x MT-3	MT-3	48	40	95	2
TSOC 40 x MT-4	MT-4	-	40	142	3
TSOC-C 50 x MT-1	MT-1	60	50	100	1
TSOC-C 50 x MT-2	MT-2	60	50	100	1
TSOC-C 50 x MT-3	MT-3	60	50	115	1
TSOC-C 50 x MT-4	MT-4	60	50	142	1